

BUILDING INSPECTION NOTICE

B-Complete; E-Complete; M-Complete; P-Complete

Permit #: 19-124996-RS

LI: Chris Rausis

Supervisor Tel: 408 535-6873

Confirmation #: 01836520 Received: 08/05/2019 By: Internet Preferred: Scheduled: 08/22/19
Tract: 571 Lot: 10 # of Units: 0 Map: 833 E 6

Address: 2351 NEWHALL ST SAN JOSE

Contact: AsafBarZvi

Phone: 7143662943

ETA Call: Y

Owner: NAISH ROBERT R AND SUSANN M

Home: (408)243-3813

Contractor: LEMON REMODELING

Work: (408)883-0191

Folder Name: (BEPM 100%)ALTERATION

Subtype: Single Family

Work Proposed: Additions/Alterations

Comments: prefer afternoon inspection if possible.

Related Permits:

Next Inspections Suggested

Insp Time:

30

Inspection time listed at the left includes 10 minutes travel time.

Number of Units:

01

Time inspection completed

Code			Description	O	P	C	N	N	R	Code			Description	O	P	C	N	N	R				
	K	A	N	R	N	F					K	A	N	R	N	F							
2	3	5	U/F Mechanical							3	4	2	Ins Shear			X							
3	4	5	Roof Structure/Nail	X																			
4	2	1	Top-out	X																			
4	2	5	Rough Gas Piping	X																			
4	3	3	Rough Ducts/Flues			X																	
4	4	4	Rough Frame			X																	
5	4	5	Insulation				X																
9	3	8	Mechanical Final				X																
2	2	5	U/F Plumb	X																			
2	4	3	U/F Frame	X																			

Inspection Code: OK = Approved, PA = Partial Approval, CN = Correction Notice, NR = Not Ready, NN = Not Necessary, RF = Re-Inspection Fee Due

Remarks: 342 - Provide 1-35 From Top Plate TO Roof sheety in line at Roof Nails - 1-35 @ 24" O.C.
433 - Insulation Enclosure over flow mechanical - Strap up plenum. Roll out protection in front of FDU
444 - Seal All Plate penetrations + Install Renc slider.

OK TO Insulate.

You have a total of -0.34 hour(s) remaining on this project as of Wednesday, August 21, 2019 2:29:09 PM.

Inspector's Signature:

Print:

MTurner

Date:

08/22/19

Page: of